

EGR Valves 88259R/ 88260R/ 88271R

A problem related to these valve models is that the position signal remains in error, despite the fact that the adaptation procedure may have been performed correctly. This issue is mainly noticed on 1.6 TDI engines.

However, before proceeding to the part's replacement, it is strongly recommended to try the following procedure:

- 1) Connect the diagnostic tool to the OBD and start the vehicle.
- 2) Keep the engine at idle speed until it reaches the optimum operating temperature, usually that is when the Fan intervenes.
- 3) With the engine heated proceed to clear the error.
- 4) The error code from that moment should no longer be present.

You should replace the valve only when you are sure that no other engine components are problematic.

88259R



88260R



88271R

