

VACUUM PUMP KITS

Differences between the 3 repair kits for vacuum pump 8091019.

When a repair kit for vacuum pump 8091019 is requested, we need to ask 2 questions:

1. Is it a Bosch installation? In this case we must give kit 8091108 .
2. Is it a Luk installation? In this case we must ask for the original code and based on this code the possible kits are 8091109 or 8091111.

Please take notice of the following information:

KIT 8091108 (for a Bosch vacuum pump) repairs the pump with VAG code 038145209A , Bosch origin.

KIT 8091109 (for a Luk vacuum pump) repairs the pump with VAG 038145209E, 038145209H, 038145209K , Luk origin (series I).

KIT 8091111 (for Luk vacuum pump) repairs the pump with VAG codes 038145209M, 038145209Q, Luk origin (series II).

