

# Scheda Tecnica: FLESSIBILI E TUBAZIONI ARIA



#### **AVVERTENZE IMPORTANTI**

Assicurarsi che il motore sia **spento e freddo** prima di intervenire. Scollegare la batteria quando previsto dalle procedure del costruttore. Eseguire diagnosi e apprendimento/adattamento quando richiesto dalla casa auto.

## Sotto-tipi

- Tubi flessibili di aspirazione aria
- Tubi rigidi di aspirazione aria
- Tubazioni intercooler
- Tubi di sovralimentazione
- Tubi di ricircolo aria

# Descrizione generale

Componenti del sistema di aspirazione e sovralimentazione che convogliano aria dal filtro all'ingresso motore, garantendo il corretto flusso d'aria per la combustione e la gestione delle emissioni.

## Anomalie più comuni

#### Sintomi lato veicolo / utente

- Perdita di potenza motore
- Rumori di sfiato o sibilo durante accelerazione
- Aumento consumi carburante
- Accensione spia motore (MIL)
- Irregolarità di minimo

#### Evidenze lato diagnosi / strumento

- Valori di pressione aria di aspirazione anomali
- Codici errore relativi a flusso aria o pressione sovralimentazione
- Dati sensori massa aria (MAF) incoerenti
- Registrazione di perdite di pressione nel sistema di aspirazione

## Cause principali del guasto

#### **Elettriche**

- Dipende da OEM; generalmente non applicabile direttamente ai tubi e flessibili.
- Sensori associati al sistema di aspirazione possono causare errori correlati.
- Cavi o connettori danneggiati possono influire sulla lettura dei sensori.

#### Meccaniche

- Rottura o crepe nei tubi flessibili
- Allentamento o rottura delle fascette di serraggio
- Ostruzioni o schiacciamenti delle tubazioni
- Deformazioni dovute a calore o vibrazioni
- Perdite di tenuta alle giunzioni

#### **Ambientali**

- Invecchiamento e deterioramento per esposizione a oli, carburanti o agenti atmosferici
- Surriscaldamento e danni termici
- Contaminazione da polveri o detriti

## **Software / Adattamento**

- Dipende da OEM; generalmente non richiesto adattamento software per sostituzione tubi flessibili. Eventuali reset errori tramite diagnosi.
- Ricalibrazione sensori aria può essere necessaria in casi specifici.

## Codici errori più comuni

CODICE	DESCRIZIONE	TIPO
P0171	Sistema troppo magro (banco 1) - possibile perdita aria aspirazione	EOBD
P0299	Sovralimentazione insufficiente - possibile perdita tubazioni turbo	EOBD
P0101	Sensore massa aria - prestazioni fuori specifica	EOBD
P0102	Sensore massa aria - segnale basso	EOBD

## Procedura di diagnosi

#### Attrezzi di prova

- Autodiagnosi
- Ispezione operative e visiva

#### Passi operativi

- 1. Collegare strumento di diagnosi e leggere codici errore
- 2. Ispezionare visivamente tubi e flessibili per crepe, rotture o allentamenti
- 3. Verificare serraggio fascette e giunzioni
- 4. Controllare valori sensori massa aria e pressione sovralimentazione
- 5. Eseguire test di tenuta pressione aspirazione con banco prova o apposito strumento

#### Procedura di Installazione

- 1. Assicurarsi che il motore sia freddo e che il sistema di aspirazione sia depressurizzato prima di intervenire.
- 2. Rimuovere il tubo o flessibile danneggiato
- 3. Pulire le superfici di accoppiamento da sporco e residui
- 4. Installare il nuovo tubo assicurandosi che sia correttamente posizionato
- 5. Serrare le fascette di serraggio secondo specifiche OEM
- 6. Verificare l'assenza di pieghe o schiacciamenti
- 7. Eseguire un controllo visivo finale

#### Procedura di test su vettura

- Avviare il motore e monitorare i parametri aria aspirata
- Verificare assenza di rumori anomali o perdite d'aria
- Controllare che non si accendano spie di errore
- Effettuare prova su strada per valutare risposta motore
- Ripetere diagnosi per confermare assenza di codici errore

#### Note di sicurezza

- Indossare guanti protettivi durante la manipolazione di componenti caldi o sporchi
- Evitare di danneggiare sensori collegati durante la sostituzione
- Non utilizzare tubi non conformi alle specifiche OEM
- Smaltire i componenti usati secondo normativa ambientale vigente



# Technical Sheet: AIR HOSES AND FLEXIBLES



#### **IMPORTANT WARNINGS**

Ensure that the engine is **off and cold** before intervening. Disconnect the battery when required by manufacturer procedures. Perform diagnosis and learning/adaptation when required by the car manufacturer.

## **Sub-types**

- Flexible air intake hoses
- Rigid air intake pipes
- Intercooler piping
- Boost pipes
- Air recirculation hoses

## **General Description**

- Components of the intake and forced induction system that channel air from the filter to the engine inlet, ensuring the correct airflow for combustion and emissions management.

#### **Most Common Anomalies**

#### **Vehicle / User Side Symptoms**

- Loss of engine power
- Hissing or whistling noises during acceleration
- Increased fuel consumption
- Check Engine Light (MIL)
- Idle irregularities

#### Diagnostic / Tool Side Evidence

- Abnormal intake air pressure values
- Error codes related to air flow or boost pressure
- Inconsistent mass air flow (MAF) sensor data
- Recording of pressure leaks in the intake system

### **Main Causes of Failure**

#### **Electrical**

- Depends on OEM; generally not directly applicable to pipes and hoses.
- Sensors associated with the intake system may cause related errors.
- Damaged wires or connectors can affect sensor readings.

#### Mechanical

- Breakage or cracks in flexible hoses
- Loosening or breakage of the clamping straps
- Obstructions or crushes in the piping
- Deformations due to heat or vibrations
- Sealing leaks at joints

#### **Environmental**

- Aging and deterioration due to exposure to oils, fuels, or atmospheric agents
- Overheating and thermal damage
- Contamination from dust or debris

## **Software / Adaptation**

- It depends on the OEM; generally, no software adaptation is required for the replacement of flexible hoses. Any error resets via diagnostics.
- Air sensor recalibration may be necessary in specific cases.

#### **Most Common Error Codes**

CODE	DESCRIPTION	TYPE
P0171	Too lean system (bank 1) - possible intake air leak	EOBD
P0299	Insufficient boost - possible turbo piping leak	EOBD
P0101	Mass air sensor - performance out of specification	EOBD
P0102	Mass air sensor - low signal	EOBD

## **Diagnostic Procedure**

#### **Test Tools**

- Self-diagnosis
- Operational and visual inspection

#### **Operational Steps**

- 1. Connect the diagnostic tool and read error codes
- 2. Visually inspect hoses and flexible lines for cracks, breaks, or looseness
- 3. Check the tightness of clamps and joints
- 4. Verify mass air sensor and boost pressure values
- 5. Perform intake pressure leak test with a test bench or specialized tool

#### **Installation Procedure**

- 1. Make sure the engine is cold and the intake system is depressurized before proceeding.
- 2. Remove the damaged hose or flexible pipe
- 3. Clean the mating surfaces of dirt and debris
- 4. Install the new hose ensuring it is correctly positioned
- 5. Tighten the clamps according to OEM specifications
- 6. Check for any kinks or crushes
- 7. Perform a final visual inspection

### **Vehicle Test Procedure**

- Start the engine and monitor the intake air parameters
- Check for any abnormal noises or air leaks
- Ensure that no error warning lights are illuminated
- Conduct a road test to evaluate engine response
- Repeat diagnostics to confirm the absence of error codes

## Safety Notes

- Wear protective gloves when handling hot or dirty components
- Avoid damaging connected sensors during replacement
- Do not use hoses that do not comply with OEM specifications
- Dispose of used components in accordance with current environmental regulations

