

---

### Crankshaft Sensor 87176 and 87484

In its newest models, Renault has modified the Crankshaft Sensor. The new Sensor differs from the previous one in the pin connector, and its colour is blue instead of black.

Renault no longer produces the black Sensor.

Hoffer will maintain both types in its range. In case a vehicle's original Crankshaft Sensor was black, the suitable Sensor would be **MD 87176**, while in case it was blue, the suitable Sensor would be **MD 87484**.

