

EGR Valve 88094 – DIAGNOSTICS PROBLEM

A frequent problem related to this EGR valve is the following:

- Engine failure light on
- EGR valve stuck in the fully open or closed position
- Generic P0400 fault code appears when connecting the diagnostic device OBD

This problem is not attributable to the EGR valve, but to a lack of software update that makes driving the EGR valve problematic.

The solution to this problem is to be found in a control unit software update. You should search for Opel Zafira B through TIS2Web or from Global TIS DVD 17.0, or for Opel Astra H Vectra C and always on TIS2Web from 22/03/2010.

At the occurrence of this problem it is recommended to find an Opel authorized workshop and request a software update, before attributing the problem to a faulty EGR valve.

Please be reminded that the EGR valve, being a component of the exhaust gas recirculation system, when found problematic that is usually a consequence of a problem and certainly not a cause.

