

### VACUUM PUMP KITS

Differences between the 3 repair kits for vacuum pump 91019.

When a repair kit for vacuum pump 91019 is requested, we need to ask 2 questions:

1. Is it a Bosch installation? In this case we must give kit 91108 .
2. Is it a Luk installation? In this case we must ask for the original code and based on this code the possible kits are 91109 or 91111.

Please take notice of the following information:

KIT 91108 (for a Bosch vacuum pump) repairs the pump with VAG code 038145209A , Bosch origin.

KIT 91109 (for a Luk vacuum pump) repairs the pump with VAG 038145209E, 038145209H, 038145209K , Luk origin (series I).

KIT 91111 (for Luk vacuum pump) repairs the pump with VAG codes 038145209M, 038145209Q, Luk origin (series II).

