

Fuel Pump

Code: **76970**

PSA APPLICATIONS

We would like to bring to your attention some important facts concerning the installation of fuel pump 76970.

There have been some returns of pumps that work correctly but have their connection partly detached from its position. For this reason a correct electrical connection can no longer be guaranteed and in fact from time to time it would be completely lost.

Attention should be given not to force the electrical connection while inserting the pump in its position. After the pump is inserted please ensure that the connection is strong. Please take under consideration the length of the wires. In some applications you may need to lengthen them further.

We kindly remind you that for every repair it is of vital importance to empty and clean the fuel tank. Dirt is one of the most frequent reasons for fuel pump malfunctioning.

